#### **INSTRUCTION MANUAL**

HI 96732

# **Dissolved Oxvaen** ISM

Dear Customer.

Thank you for choosing a Hanna product. This manual will provide you with the necessary information for the correct use of the instrument. Please read it carefully before using the meter. If you need additional technical information, do not hesitate to e-mail us at tech@hannainst.com.

### **Preliminary examination:**

Please examine this product carefully. Make sure that the instrument is not damaged. If any damage occured during shipment, please notify vour Dealer.

Each HI 96732 Ion Selective Meter is supplied complete with:

- Two Sample Cuvettes and Caps
- 9V Battery
- Instruction Manual

Note: Save all packing material until you are sure that the instrument works correctly. Any defective item must be returned in its original nackina.




 $|oldsymbol{i}|$  For more details about spare parts and accessories see "Accessories".

Technical specifications:	
Range	0.0 to 10.0 mg/L
Resolution	0.1 mg/L
Accuracy	$\pm 0.4$ mg/L $\pm 3\%$ of reading @ 25°C
Typical EMC Dev.	$\pm$ 0.1 mg/L
Light Source	Light Emitting Diode
Light Detector	Silicon Photocell with 466 nm filter
Method	Adaptation of the Standard Methods for Examination of Water and Wastewater (18th edition), azide modified Winkler method. The reaction between dissolved oxygen and the reagent causes a yellow tint in the sample.
Environment	0 to 50°C (32 to 122°F); max 95% RH non-condensing
Battery Type	1 x 9 volt
Auto-Shut off	After 10' of non-use in measurement mode; after 1 hour of non-use in calibration mode; with last reading reminder.
Dimensions	192 x 104 x 69 mm (7.6 x 4.1 x 2.7")
Weight	360 g (12.7 oz.).

# HANNA<sup>®</sup> instruments www.hannainst.com

### Functional description:



- 1. GLP/A kev: press to enter GLP mode. In calibration mode press to edit the date and time
- 2. CAL CHECK key: press to perform the validation of the meter, or press and hold for three seconds to enter calibration mode.
- 3. **ZERO/CFM** key: press to zero the meter prior to measurement, to confirm edited values or to confirm factory calibration restore.
- 4. **READ**/▶ kev: In *measurement mode*, press to make a measurement. In GLP mode press to view the next screen.
- 5. **ON/OFF** key: to turn the meter on and off.
- 6. Liquid Crystal Display (LCD)
- 7. Cuvette alianment indicator
- 8 Cuvette holder

#### DISPLAY ELEMENTS DESCRIPTION:



- 1. The measuring scheme (lamp, cuvette, detector), appears during different phases of zero or reading measurement
- 2. Error messages and warnings
- 3. The battery icon indicates the charge state of the battery
- 4. The hourglass appears when an internal check is in progress
- 5. Status messages
- 6. The chronometer appears when the reaction timer is running
- 7. The month, day and date icons appear when a date is displayed
- 8. Four digit main display
- 9. Measuring units
- 10. Four digit secondary display

#### **Errors and warnings:**

#### ON ZERO READING:



Light High: There is too much light to perform a measurement. Please check the preparation of the zero cuvette.



**Light Low:** There is not enough light to perform a measurement. Please check the preparation of the zero cuvette



No Light: The instrument cannot adjust the liaht level. Please check that the sample does not contain any debris.

#### ON SAMPLE READING:



**Inverted cuvettes:** The sample and the zero cuvette are inverted.



Zero: A zero reading was not taken. Follow the instructions of the measurement procedure for zeroina the meter.



Under range: A blinking "0.00" indicates that the sample absorbs less light than the zero reference. Check the procedure and make sure you use the same cuvette for reference (zero) and measurement



Over Range: A flashing value of the maximum concentration indicates an over range condition. The concentration of the sample is beyond the programmed range: dilute the sample and re-run the test.

#### DURING CALIBRATION PROCEDURE



Standard Low: The standard reading is less than expected.



Standard High: The standard reading is higher than expected.

#### OTHER ERRORS AND WARNINGS:



Cap error: Appears when external light enters in the analysis cell. Assure that the cuvette cap is present.



Cooling lamp: The instrument waits for the lamp to cool down.



**Battery low:** The battery must be replaced soon.



Dead battery: This indicates that the battery is dead and must be replaced. Once this indication is displayed, normal operation of the instrument will be interrupted. Change the hattery and restart the meter

### Measurement procedure:


**Measurement ▼** 




LCD displays dashes, the meter is ready. The blinking "ZERO" indicates that the instrument needs to be zeroed first.

1 • Turn the meter on by pressing ON/OFF.

2. When the beeper sounds briefly and the






the reading **5•** Invert several times the bottle. The sample becomes orange-vellow and a flocculant agent will appear. Let the sample stand and the



5

X5 X X5 X

flocculant agent will start to settle. 6. After approximately 2 minutes, when the upper half of the bottle becomes limpid. add 10 drops of HI 93732C-0.



**8•** Fill the cuvette up to the mark with 10 mL of the unreacted (original) sample, and replace the cap. This is the blank.



**9•** Place the cuvette into the holder and ensure that the notch on the cap is positioned securely into the groove.




10 • Press ZERO/CFM and the lamp, cuvette and detector icons will appear on the display. depending on the measurement phase. After a few seconds the display will show "-0.0-". The meter is now zeroed and ready for measurement. Remove the cuvette



10

- 11 Fill another cuvette up to the mark with 10 mL of the reacted sample and replace the
- 12 Replace the cuvette into the holder and ensure that the notch on the cap is positioned securely into the groove.
- **13** Press **READ/** and in all cases the lamp cuvette and detector icons will appear on 13 READ phase.
- 14 The instrument directly displays the on the LCD.




#### CALIBRATION

Note: It is possible to interrupt the calibration procedure at any time by pressing CAL CHECK or ON/OFF keys

- 1 Turn the meter on by pressing ON/OFF.
- 2. When the beeper sounds briefly and the LCD displays dashes, the meter is ready.
- to enter calibration mode. The display will show "CAL" during calibration procedure. The blinking "ZERO" asks for instrument zeroing.
- holder and ensure that the notch on the cap is positioned securely into the groove.
- **5** Press **ZERO/CFM** and the lamp, cuvette and detector icons will appear on the display. depending on the measurement phase.
- **6** After a few seconds the display will show "-0.0-". The meter is now zeroed and ready for calibration. The blinking "READ" asks for reading calibration standard.
- **7** Remove the cuvette.
- 8 Place the CAL CHECK™ Standard HI 96732-11 Cuvette B into the holder 9-10 and ensure that the notch on the cap is positioned securely into the groove.
- **9** Press **READ/** and the lamp, cuvette and detector icons will appear on the display, depending on the measurement phase.
- the CAL CHECK™ standard value.
- Note: If the display shows "STD HIGH". the standard value was too high. If the display shows "STD LOW", the standard value was too low. Verify that both CAL CHECK™ Standard HI 96732-11 Cuvettes, A and B are free from fingerprints or dirt and that they are inserted cor-



51






ZERO CFM

l sue l zero

0.0 -

50.



11 • Then the date of last calibration (e.a.:

"01.08.2009") appears on the display, or

"01.01.2009" if the factory calibration

was selected before. In both cases the year

number is blinking, ready for date input.

(2009-2099). If the key is kept pressed.

the year number is automatically increased.

7FRO/CFM or RFAD/► to confirm Now

the display will show the month blinking.

(01-12). If the key is kept pressed, the

month number is automatically increased.

press **ZERO/CFM** or **READ/** to confirm.

Now the display will show the day blinking.

(01-31). If the key is kept pressed, the

day number is automatically increased.

14 • Press GLP/▲ to edit the desired month


15 • When the correct month has been set.

16 • Press GLP/▲ to edit the desired day

13. When the correct year has been set, press

12 • Press GLP/▲ to edit the desired vegr





19 • The instrument will return automatically to *measurement mode* by displaying dashes on the LCD.



0,10,8

GLP

**\_20009**4

100

2009

GLP

ZERO OF READ

0908

2009

GLP



#### GLP

calibration can be restored

#### LAST CALIBRATION DATE

secondary display.

2. If no calibration was performed, the factory calibration message. "F.CAL" will appear on the main display and the instrument returns to measurement mode after three seconds.





#### FACTORY CALIBRATION RESTORE

factory calibration.





**3** Press **7FRO/CFM** to restore the factory calibration or press GLP/A again to abort factory calibration restore.

## **Factory** Calibration

Restore w





upon restoration of factory calibration prior to returning to *measurement mode*.



#### Warrantv

**Accessories:** 

REAGENT SETS

HI 93732-01

HI 93732-03

HI 96732-11

HI 721310

HI 731318

HI 731331

HI 731335

HI 93703-50

OTHER ACCESSORIES

HI 96732 is warranted for two years against defects in workmanship and materials when used for its intended purpose and maintained according to the instructions

CAL CHECK™ Standard Cuvettes (1 set)

Tissue for wiping cuvettes (4 pcs)

Cuvettes cleaning solution (230 mL).

This warranty is limited to repair or replacement free of charge.

Reagents for 100 tests

Reagents for 300 tests

9V battery (10 pcs)

Glass cuvettes (4 pcs)

Caps for cuvettes (4 pcs)

Damages due to accident, misuse, tampering or lack of prescribed maintenance are not covered

If service is required, contact your dealer, If under warranty, report the model number, date of purchase, serial number and the nature of the failure. If the repair is not covered by the warranty, you will be notified of the charges incurred.

If the instrument is to be returned to Hanna Instruments, first obtain a Returned Goods Authorization Number from the Customer Service Department and then send it with shipment costs prepaid. When shipping any instrument, make sure it is properly packaged for complete protection.

To validate your warranty fill out and return the enclosed warranty card within 14 days from the date of purchase.

Before using these products, make sure that they are entirely suitable for your specific application and for the environment in which they are used. Operation of these instruments may cause unacceptable interferences to other electronic equipments, this

requiring the operator to take all necessary steps to correct interferences. Any variation introduced by the user to the supplied equipment may degrade the instrument's EMC

To avoid damages or burns, do not put the instrument in microwave oven. For yours and the instrument safety do not use or store the instrument in hazardous environments.

Hanna Instruments reserves the right to modify the desian, construction and appearance of its products without advance notice


For additional information, contact your dealer or the nearest

**Hanna Customer Service Center.** To find the Hanna Office in your area. visit our web site

www.hannainst.com



In GIP mode the last calibration date can be verified and the factory









• Extract the battery from its location and replace it with a fresh one.


• Insert back the battery cover and turn it clockwise to close.

Validation **▼** 

XED I ZERO

- [],[] -

ۥ>



# INTERFERENCES

Interference may be caused by reducing and oxidizing materials.

# Validation and Calibration procedures

Warning: do not validate or calibrate the instrument with standard solutions other than the Hanna CAL CHECK™ Standards otherwise erroneous results will be obtained

For accurate validation and calibration results please perform tests at room temperature (18 to  $25^{\circ}$ C: 64.5 to  $77.0^{\circ}$ F).


*i* Use the Hanna CAL CHECK™ cuvettes (see "Accessories") to validate or calibrate instruments.

#### VALIDATION

1 • Turn the meter on by pressing ON/OFF. 3

2. When the beeper sounds briefly and the LCD displays dashes, the meter is ready.

3. Place the CAL CHECK™ Standard
4.5 and ensure that the notch on the can is positioned securely into the groove.




**5**• After a few seconds the display will show "-0.0-". The meter is now zeroed and ready for validation.

6. Remove the cuvette

**7** • Place the CAL CHECK™ Standard HI 96732-11 Cuvette B into the holder and ensure that the notch on the cap is positioned securely into the groove.

8. Press CAL CHECK key and the lamp. cuvette and detector icons together with "CAL CHECK" will appear on the display. depending on the measurement phase.










3. Press and hold CAL CHECK for three seconds

4. Place the CAL CHECK™ Standard 5-6



10 • The instrument will show for three seconds














# **Battery management**

To save the battery, the instrument shuts down after 10 minutes of non-use in *measurement mode* and after 1 hour of non-use in *calibration* mode

If a valid measurement was displayed before auto-shut off, the value is displayed when the instrument is switched on. The blinking "ZERO" means that a new zero has to be performed.



One fresh battery lasts for arround 750 measurements, depending on the

The remaining battery capacity is evaluated at the instrument startup and after each measurement

The instrument displays a battery indicator with three levels as follows:

- 3 lines for 100 % capacity
- 2 lines for 66 % capacity
- 1 line for 33 % capacity

• Battery icon blinking if the capacity is under 10 %. If the battery is empty and accurate measurements can't be taken any

more the instrument shows "dEAd bAtt" and turns off. To restart the instrument, the battery must be replaced with a fresh one. To replace the instrument's battery, follow the steps:

- Turn the instrument off by pressing ON/OFF.
- Turn the instrument upside down and remove the battery cover by turning it counterclockwise.

